



Practitioner's Docket No. MUH-12752

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number : US 6,765,836 B2
Patentee : Ullrich Menczigar
Issued : Jul. 20, 2004
Art Unit : 2824
Examiner : Andrew Q. Tran
Title : Synchronization Device for a Semiconductor Memory Device
Docket No. : MUH-12752
Customer No. : 24131

Certificate

AUG 04 2004

Commissioner for Patents

of Correction

P.O. Box 1450,

Alexandria, VA 22313-1450

**ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue
Division**

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R.1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.
2. The Document where the errors are shown correctly in the application file are:

The Foreign Application information appears correctly on the first page of the Declaration filed on October 28, 2003 and on the Filing Receipt dated December 15, 2003 received from the U.S. Patent and Trademark Office. The Certified Priority document was filed in the U.S. Patent and Trademark Office on October 28, 2003.

3. Please send the Certificate to:

Name : LERNER AND GREENBERG, P.A.
Address : P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

Assignment recorded on _____

Reel : _____
Frame : _____

Werner H. Steiner
(name of authorized person signing)

WERNER H. STEINER

REG. NO. 34,956

Attorney of Record

Title of authorized person signing

Attached is a Recordal of assignment

Attached is a "CERTIFICATE UNDER 37 CFR 3.73(b)"
(establishing the right of the assignee to take action in this case)

Date: _____

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,765,836 B2
ISSUED : Jul. 20, 2004
INVENTOR(S) : Ullrich Menczigar

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Item [30] should read as follows:

Sep. 10, 2002 (DE) 102 41 928

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,765,836

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,765,836 B2
ISSUED : Jul. 20, 2004
INVENTOR(S) : Ullrich Menczigar

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Item [30] should read as follows:

Sep. 10, 2002 (DE) 102 41 928

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,765,836

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.